

COOPERATION WITH ORGANIZATIONS IN TECHNICAL PRACTICE IN THE FIELD OF MATERIALS ANALYSIS

Marián Hazlinger – Vladimír Kuracina – Roman Moravčík

Institute of Materials Science

ABSTRACT

Metallographic analysis of semi products, heat and chemical-heat treatment of components. Analysis of the causes of components damage. Mechanical tests of materials.

CONCLUSIONS

I believe we don't disappoint the trust with which customers and partners approach us in solving the production problems.

REFERENCES

- Puškár, A., Hazlinger, M. Porušovanie a lomy súčastí. ŽU Žilina, EDIS, 2000. ISBN 80-7100-654-8.
- Hazlinger, M., Moravčík, R., Čaplovič, Ľ. Degradáčnne procesy a predikcia životnosti materiálov, nakladateľstvo STU, 2010. ISBN 978-80-227-3334-2.
- Hazlinger, M., Moravčík, R. Chemicko-tepelné spracovanie materiálov, nakladateľstvo STU, 2013. ISBN 978-80-227-3924-5.
- Moravčík, R., Čička, R., Hazlinger, M., Hvizdoš, P., Janovec, J. Úvod do materiálového inžinierstva I, nakladateľstvo STU, 2015. ISBN 978-80-227-4405-8.
- Hazlinger, M. Analýza súčastok poškodených únavou. Analysis of fatigue damaged components. In: Materials Science and Technology [online]. ISSN 1335-905, roč. 6, č. 3 (2006).
- Hazlinger, M., Moravčík, R. Analýza súčastok poškodených únavou materiálu. In: Vedecké práce MTF STU v Bratislave so sídlom v Trnave. Research papers Faculty of Materials Science and Technology Slovak University of Technology in Trnava. č. 25 (2008), s. 45-50. ISSN 1336-1589.
- Szmolka, T., Hazlinger, M., Kocúrová, K. Damaged spindle analysis of motorcycle's wheel. In: Letná škola únavy materiálov, 2010. ŽU Žilina. ISBN 978-80-554-0235-2, s. 194-197.
- Kocúrová, K., Hazlinger, M. Crack reason analysis of damaged carbonitrided part. In: Materials Engineering. ISSN 1335-0803, 17, No. 1 (2010), p. 29-33.
- Kocúrová, K., Dománková, M., Hazlinger, M. The influence of carbonitriding process on microstructure and mechanical properties of micro-alloyed steel. In: *Metalurgija*. Vol. 52, No. 1 (2013), p. 19-22. ISSN 0543-5846.
- Hazlinger, M., Moravčík, R. Degradation Processes and Life-Time Prediction. Plzeň: Aleš Čeněk, 2017, 310p. ISBN 978-80-7380-670-5.

CONTACT

marian.hazlinger@stuba.sk


Cooperation with organizations in the field:

- Mechanical tests of materials – tensile test, hardness test, impact test
- Metallographic analysis – analysis of the causes of components damage, fractography of fracture surface and microstructure of materials
- Quality evaluation of heat and chemical-heat treatment of materials
- Workers training

Examples of analysed components:



Metallographic analysis microstructure of materials



Mechanical properties of materials - impact tests, tensile tests

